Unique Id: 009D4730-5D8D0BE0-1C02A1 Copyright 1999 Compaq Computer Corporation. All rights reserved SOURCE: Compaq Computer Corporation INFORMATION BLITZ INFORMATION BLITZ TITLE: Errors from Oracle 8.0.4.x / DIGITAL UNIX / EV6 under heavy load DATE: 26-Feb-1999 INFORMATION BLITZ #: 2610-CR AUTHOR: Henry Bone TEL#: 603-884-6288 (DTN 264-6288) EMAIL: Henry. Bone@digital.com DEPARTMENT: UNIX Business Segment ______ PRODUCT NAME(S) IMPACTED: DIGITAL UNIX V4.0E PRODUCT FAMILY(IES): PRODUCT NUMBERS: Storage Systems Networks ____ PC ____ Software V4.0E Other (specify) ____ PROBLEM STATEMENT:

[TD 2610-CR] Errors from Oracle 8.0.4.x w/DUNIX & EV6 Under Heavy Load

Customers who ran successfully with heavy loads on EV56 Tlasers under DIGITAL UNIX, Oracle 8.0.4.x have reported experiencing fatal "ORA 600 [512] Error." after upgrading to EV6 CUPs.

This problem only manifests itself in rare cases when running heavy loads, as with Oracle, SAP, etc. If your are running in a configuration where Oracle will put a heavy load on the system it is recommended that you defer upgrading to the EV6 CPUs until we have developed a fix for the problem. Compaq has teams of engineers working non stop to fix the problem.

SOLUTION:

There is no solution at this time, the only known workaround is to go

back to the previous CPU boards that were working without problems. If this is a new systems and you don't have old EV56 boards, contact your Compaq Field Service office.

ADDITIONAL COMMENTS:

UNIX Support Engineering Group, UNIX Development Engineers and Tlaser Hardware Engineering are working non-stop to develop a fix for the problem, Oracle's Problem Evaluation and Resolution Engineering group is also heavily involved, to assist in isolating the problem and to ensure that a solid fix is provided.

NOTE: This problem only manifests itself in rare cases when running heavy loads, as with Oracle, SAP, etc. If your are running in a configuration with Oracle and a heavy load on the system and you are planning to upgrade, please defer the upgrad to EV6 until we have developed a fix for the problem. Compaq is using all available resources to fix this problem as soon as possible.

If a user should experience this problem our engineer has requested that they open an IPMT case and collect the following:

- o If there is a core file left after the Oracle crash, please please include it in the escalation.
- o Please provide the firmware revision on the TL6 boards, this can be retrieved by: P00>>sho version P00>>sho pal
- o Please provide the hardware revision of the TL-6 boards (should be on the front of the module).
- o Provide the binary errlog and /var/adm/message files.
- o How many processors are in the failing system?
- o The output of "# psrinfo -v" on the EV6 system.

A subsequent Blitz will be issued when a fix becomes available.

<>UPDATE /TEXT_UPDATE/UNIQUE_IDENTIFIER="009D4730-5D8D0BE0-1C02A1" /TITLE="[TD 2610-CR] Errors from Oracle 8.0.4.x w/DUNIX & EV6 Under Heavy Load" /BADGE=(AUTHOR="999997", ENTER="134779", MODIFY="134779", EDITORIAL_REVIEW="134779", TECHNICAL_REVIEW="999997")-

```
/NAME=(AUTHOR="HENRY BONE", ENTER="LORETTA LIGHT", -

MODIFY="LORETTA LIGHT", EDITORIAL_REVIEW="LORETTA LIGHT", TECHNICAL_REVIEW="HENRY BONE

/DATE=(AUTHOR=" 1-MAR-1999", ENTER=" 1-MAR-1999", -

EXPIRE=" 1-MAR-2001", FLASH=" 1-MAR-1999 09:06:08.54", MODIFY=" 1-MAR-1999", -

EDITORIAL_REVIEW=" 1-MAR-1999", TECHNICAL_REVIEW=" 1-MAR-1999") -

/GEOGRAPHY="USA"/SITE="EIRS"/OWNER="TIM-BLITZ"-

/FLAGS=(USA_CUSTOMER_READABLE, NOPOST_MESSAGE_DISPLAY, NOLOCAL, -

EUR_CUSTOMER_READABLE, GIA_CUSTOMER_READABLE, NOINIT_MESSAGE_DISPLAY, -

EDITORIAL_REVIEWED, FIELD_READABLE, FLASH, TECHNICAL_REVIEWED, READY)
```