

Unique Id: 009D54AF-A7142BE0-1C02A1

Copyright 1999 Compaq Computer Corporation. All rights reserved

SOURCE: Compaq Computer Corporation INFORMATION BLITZ

INFORMATION BLITZ TITLE:

UNIX Workaround for EV6 PAL Code Error

DATE: 19-Mar-1999

INFORMATION BLITZ #: TD 2622-CR

AUTHOR: Tom Hayden

E-MAIL: hayden@zk3.dec.com

DEPARTMENT: UNIX Support Engineering Group

=====

PRODUCT NAME(S) IMPACTED: Compaq's DIGITAL UNIX V4.0E

PRODUCT FAMILY(IES):

PRODUCT NUMBERS:

Storage	_____	
Systems	<u> X </u>	DS20, ES40, GS60, GS140
Networks	_____	_____
PC	_____	_____
Software	<u> X </u>	DIGITAL UNIX V4.0E
Other (specify)	_____	_____

PROBLEM STATEMENT:

Compaq and Oracle recently received a few reports from their customers of occurrences of a fatal Oracle error - ORA 600 [512] - when running under DIGITAL UNIX V4.0E on Compaq GS60 and GS140 (EV6) systems. This problem was not experienced on any other hardware platform or operating system. This problem was not caused by the Oracle products in use.

SOLUTION:

After an intensive investigation, a joint Compaq and Oracle hardware and software engineering team has isolated the problem. Even though, to date, the problem has occurred only on systems running Oracle, it is not an Oracle problem. It is theoretically possible for the underlying

problem to occur on DIGITAL UNIX DS20, ES40, GS60, and GS140 systems not running Oracle, though that has not happened to the best of our knowledge.

The source of the problem has been identified as a flaw in a particular path of the EV6 PAL code used in DS20, ES40, GS60, and GS140 systems running DIGITAL UNIX. Compaq has developed new PAL code to fix this problem in these systems and is currently testing the code extensively. A release date for the new PAL code is not yet available.

In the meantime, as a temporary workaround, Compaq has developed a change to DIGITAL UNIX V4.0E which will prevent the problem from occurring. This workaround is now available from Compaq Services' Product Support organizations. Please specify that you need the "UNIX Workaround for the EV6 PAL Code Error".

\ In the customer viewable portion of this Blitz, customers are
\ being notified that this workaround is now available from Compaq
\ Services' Product Support organizations. Customers are being advised
\ to request the "UNIX Workaround for the EV6 PAL Code Error".
\ It is important that we track every customer who receives this
\ workaround. Compaq product support groups which receive requests
\ for this workaround must request it on a case-by-case basis via
\ e-mail to the USEG (UNIX Support Engineering Group). Please send
\ your requests to:

\ unxev6wa@zk3.dec.com

\ In the e-mail request you must include: the name of the Compaq
\ employee making the request to USEG, the CHAMPS or other problem
\ tracking system ID of the customer's original request, the
\ customer's company and address, and a person at the customer site
\ who can be contacted if needed.
\ USEG's response will include a pointer to where the workaround can
\ be obtained.

NOTES:

(1) DIGITAL UNIX V4.0E Patch Kit 1 (BL1) must be installed before this workaround is applied.

(2) This workaround must be applied to all DS20, ES40, GS60, and GS140 systems running DIGITAL UNIX until the new EV6 PAL code becomes available.

(3) All DS20, ES40, GS60, and GS140 systems running DIGITAL UNIX must be upgraded to the new EV6 PAL code when it becomes available.

(4) The UNIX workaround must be removed when the new EV6 PAL code is installed.

ADDITIONAL INFORMATION:

Compaq will announce the availability of the corrected EV6 PAL code.

*****< NOTE *****

*

* INFORMATION IN THIS DOCUMENT REPRESENTS OPERATIONAL EXPERIENCES AND
* SUGGESTIONS BY COMPAQ OR PARTNER EMPLOYEES. COMPAQ SHALL NOT BE
* RESPONSIBLE FOR ANY ERRORS OR OMISSIONS CONTAINED IN THIS DOCUMENT,
* AND RESERVES THE RIGHT TO MAKE CHANGES TO IT WITHOUT NOTICE.

*

*** COMPAQ INTERNAL USE ONLY ***

```
<>UPDATE /TEXT_UPDATE/UNIQUE_IDENTIFIER="009D54AF-A7142BE0-1C02A1"-  
/TITLE="[TD 2622-CR] UNIX Workaround for EV6 PAL Code Error - BLITZ"-  
/BADGE=(AUTHOR="999997",ENTER="134779",MODIFY="134779",-  
EDITORIAL_REVIEW="134779",TECHNICAL_REVIEW="999997")-  
/NAME=(AUTHOR="TOM HAYDEN",ENTER="LORETTA LIGHT",-  
MODIFY="LORETTA LIGHT",EDITORIAL_REVIEW="LORETTA LIGHT",TECHNICAL_REVIEW="TOM HAYDEN"  
/DATE=(AUTHOR="18-MAR-1999",ENTER="18-MAR-1999",-  
EXPIRE="18-MAR-2001",FLASH="18-MAR-1999",MODIFY="19-MAR-1999",-  
EDITORIAL_REVIEW="18-MAR-1999",TECHNICAL_REVIEW="18-MAR-1999")-  
/GEOGRAPHY="USA"/SITE="EIRS"/OWNER="TIM-BLITZ"-  
/FLAGS=(USA_CUSTOMER_READABLE,NOPOST_MESSAGE_DISPLAY,NOLOCAL,-  
EUR_CUSTOMER_READABLE,GIA_CUSTOMER_READABLE,NOINIT_MESSAGE_DISPLAY,-  
EDITORIAL_REVIEWED,FIELD_READABLE,FLASH,TECHNICAL_REVIEWED,READY)
```