

 d i g i t a l 	FCO	Level of Urgency +---+ F +---+	Page_1_ Of_3_
---------------------------------------	-----	---	------------------

FIELD CHANGE ORDER	Number: 62XXM-F002-DAS
--------------------	------------------------

Applicability: This FCO should only be installed on 6000-2XX (62XX) systems that use the TK50 for making tapes that will be read on another system type (i.e., MicroVAX, VX2000, 11/785, etc.). This FCO changes the revision of the T1034 module to K3,4,5. It does not change the rev. of the 6000-2XX systems.

Problem/Symptom: An incompatibility situation can occur with TK50 tapes. The problem is caused by the TBK50 controller (T1034) using a different soft error (i.e., bad spot recovery) routine than used by TQK50, TUK50, TZK50, TQK70 and TBK70 (T1035) controllers.

Quick Check: The revision of the T1034 should be K3, K4 or K5 or check in location E81 for P/N 23-358E5-00.

Compatibility/Prerequisite FCO: N/A	Est. Time to Install: 1 Hour
--	---------------------------------

Special Tools or Test Equipment:
See page 2.

FCO	Quantity:	Part Number:	Description:
EQ-01552-02	1	T1034 module	DEBNA (Rev K3, K4 or K5)
FA-04857-03	1	FCO Document	

EQ Kit Variation System/Option Applic:	N/A
--	-----

Approvals

CSSE Engineer Ken Jackson	F.S. Product Safety Robert Brister	F.S. Logistics Bill Stanley
CSSE Manager Jan Sicard	F.S. Microfiche Libraries EP-FSNVX-LB VAX	Affected Population: 400
MicroMedia Pub. Diane MacDonald	VAXnotes STARS	Initial Kitting: 400

Revision:

A

Hardcopy Publication:

450

FCO Release Date

October 23, 1989

Parts Availability:

October 1989

d	i	g	i	t	a	l	

FCO 62XXM-F002

PAGE 2 OF 3

SPECIAL TOOLS: Continued from Page 1

Blank TK50 Tape

Field Service Tool Kit.

VELOSTAT Electrostatic Field Service Kit (P/N 29-26246-00).

I. FIELD INSTALLATION AND TEST PROCEDURE FOR 62XX Systems

=====

```
*****
*                                     *
*                   N O T E          *
*                                     *
* Prior to installing the FCO, all TK50 tapes that have been *
* created by the VAX 6000 series system should be screened by *
* attempting to read them on a non-TBK50 drive (e.g., TQK50, *
* TZK50, etc.). Tapes with soft errors will not be readable on *
* the non-TBK50 and should be backed up from the TBK50 to a mass *
* storage device such as disk or tape. Once the FCO is installed, *
* that information can be restored back to the TK50 tapes via the *
* VAX 6000 series system.          *
*****
```

1. Shut down the system by executing the Shutdown Command Procedure.

\$ @SYS\$SYSTEM:SHUTDOWN

After VMS shuts down, type ^P you will now be at the console mode prompt, >>>

At the console prompt type HALT <CR>

2. Turn the upper key switch on the system's console panel fully counterclockwise. This shuts off the output of the battery backup unit if present. To ensure "Total Off", pull the power circuit breaker on the H405 AC power controller located on the lower right side at the back of the system. Unplug the system.
3. Use ALL ESD safety precautions to prevent DOA modules in upgrade kit.

NI and TK50 functions of the T1034:

EVDYD - VAX NI Functional Diagnostic
EVMDA - VAX TK50/TK70 Exercisor
(Run EVMDA/SECTION:ACCEPTANCE)

15. Update Site Management Guide to reflect this FCO.

\^ 62XMX
\62XMX
\62XMX-F002
\JACKSON
\1989
\OCT
\FCO_DOCS