

	d	i	g	i	t	a	l
	-	-	-	-	-	-	-

FCO

 Level of
 Urgency
 [I]

 Page 1
 Of 5

FIELD CHANGE ORDER

Number: DEBET-I001

Applicability: Rework "as needed" DEBET-AA, AB, RC, RD, at Revision Level D7 or below for customers experiencing problems running RBMS. This FCO implements ECO number 54-17521-MK007 and DEBET-MK011.

Problem/Symptoms: This FCO corrects problems seen on nodes running RBMS as well as rectifying several other minor Microcode problems (see problem description for more details). It also enables a down line loading feature required to support LAN traffic monitoring.

Quick Check: 1) The unit tag located on the rear of the unit will have Revision level at "E7".

- 2) opening up the unit will reveal that;
 E131 has a ROM marked 23-293E5 &
 E132 has a ROM marked 23-294E5

Compatibility/Prerequisite FCO: N/A

 Est. Time to Install:
 1.0 hr.

Special Tools or Test Equipment: N/A

FCO Parts Information

Order by FCO Kit #	Contents		
	Quantity	Part Number	Description
EQ-01479-01	1	23-293E5	Microcode ROM
	1	23-294E5	Microcode ROM
	1	36-19209-05	Brady Marker "E"
	1	36-19208-07	Brady Marker "7"
FA-04768-01	1		FCO Document

EQ Kit Variation/System-Option Applic: DEBET family of Ethernet Bridges.

Approvals

 CSSE Engineer
 Richard Woodard

 F.S. Product Safety
 Jerry Gannelli

 F.S. Logistics
 Ed Duggan

 Responsible CSSE Mgr.
 Tony Payne

 F.S. Microfiche Libraries
 EP-FSNVX-LB VAX

 Affected Population
 400

MicroMedia Publishing

Initial Kitting

Ray LeBlanc	VAXnotes	400
Revision: A	STARS	Hardcopy Publication 500
FCO Release Date 4-NOV-87		Parts Availability October 1987

EN-01095-12-REVB(548)

```

- - - - -
|d|i|g|i|t|a|l|
|-|-|-|-|-|-|-|

```

FCO DEBET-I001

PAGE 2 OF 5

PROBLEM and ENHANCEMENT DESCRIPTION

1. Down line load feature required to support LAN Traffic Monitor.
2. BRIDGE in position to take over as ROOT, if present ROOT fails, will not notify the other BRIDGEs on the network that it is the new ROOT.
3. Flooding of the network will occur if the Ethernet address table is filled (8000 entries).
4. Bridge receiving a loopback message with an illegal "next destination" address, will forward it.

The following problems will only be seen from a node on the network that is running remote bridge management software.

5. Bridge Frame Sent counters for Link 1 and Link 2 are swapped.
6. Bridge Packet Transmit counter may not contain correct count.
7. Bridge Forwarding Entries Lost counter does not work.
8. Bridge Filter Frame counter for Link 1 contains Link 0 count.
9. Bridge may broadcast an RBMS reply message.
10. Broadcast address will be found in Address Table when Bridge is initialized.

9. Locate and remove the microcode ROM 245E5 at location E131 using an IC remover or small screwdriver, and replace with microcode ROM 293E5. (SEE FIGURE 1)
10. Locate and remove the microcode ROM 246E5 at location E132 using an IC remover or small screwdriver, and replace with microcode ROM 294E5. (SEE FIGURE 1)
11. Install Brady Markers "E" and "7" on the rear label of the DEBET, over the existing Revision of D6.
12. Reverse sequence steps 1 thru 8 to restore the DEBET back to operation.
13. Complete LARS data as per example on page 5.
14. Update Site Management Guide to reflect this FCO.

```

- - - - -
|d|i|g|i|t|a|l|
|-|-|-|-|-|-|-|

```

FCO DEBET-I001

PAGE 4 OF 5

Figures 1 and 2

```

- - - - -
|d|i|g|i|t|a|l|
|-|-|-|-|-|-|-|

```

FCO DEBET-I001

PAGE 5 OF 5

LARS

	USA & GIA	EUROPE
Activity		
Contract and warranty	W	Y
Non Contract/Non Warranty	F	F
DEC Option	DEBET	DEBET

Type of Call	M	M
Action Taken	D	I
Fail Area-Module-FCO-Comments	FCO DEBET-I001	FCO DEBET-I001
Material Used	EQ-01479-01	EQ-01479-01

\^ DEBET
\DEBET
\WOODARD
\1987
\NOV
\FCO_DOCS