_ FCO DNSBX-0001, Potential for Electrical Short in the Transformer DIGITAL FCO CATEGORY PAGE 1 [0] OF 4 FIELD CHANGE ORDER NUMBER: DNSBX-0001 APPLICABILITY: This is an "O" coded FCO and it should be installed on all DECnis 600 platforms: DNSBX-AD, DNSBA-BC/BD, DNSEA-BC/BD, DNSEB-BC/BD, DNSEC-BC/BD, DNSED-BC/BD, DNSEE-BC/BD, DNSEF-EE/BD, DNSBB-BC/BD, DNSBD-BC/BD. This FCO will replace the H7720-AA (30-36324-01) with revision "C01". PROBLEM & SYMPTOM: Under certain failure modes, there are indications for a potential cause of an electrical short in the transformer. result in the power supply overheating. The symptom is an unexpected failure of the device due to loss of power. This may be accompanied by release of smoke. This is not a safety hazard. (Continued on Page 2) SOLUTION: The solution for this problem is to replace every power supply H7720-AA below revision C01 with revision C01 or higher. However, because the DECNIS 600 is a key high-end networking product, FCO implementation will need to be scheduled in advance with customers. The customer and Field Service will need to agree and schedule a "non-critical" time to have the PSU replaced. QUICK CHECK: All good and fully tested PSUs will be at revision C01 or higher. All "suspect" PSUs will be at lower revisions; either A01, B01, B02 or B03. The revision number is situated immediately under the AC input socket. PRE/CO-REQUISITE FCO: N/A MFIT HRS 1.0 TOOL/TEST EQUIPMENT: Other than 2 flat-head screwdrivers (1 small, 1 large), no special tools or equipment are needed. FCO PARTS INFORMATION DESCRIPTION OF CONTENTS FCO KIT NO. EQ-01683-01 30-36324-01 Power Supply, Rev C01 FA-05020-01 FIELD APPLICATION (FA) DOCUMENT FCO CHARGING INFORMATION (See Last Page) APPROVALS TECH. ENGINEER ENG. BUSINESS MGR. DS LOGISTICS DS PRODUCT SAFETY Charng-Ming Yeh Richard Benwell |Moshe Roditi Robert Brister MICROMEDIA PARTS AVAILABILITY FCO REVISION FCO RELEASE DATE Brenda Rogers February 14, 1994 February 3, 1994 В

+						+
D	i	q	İi	İt	j a	İlİ
İ						
					' 	
•						•

FCO DNSBX-0001

PAGE 2 OF 4

PROBLEM & SYMPTOM: (Continued from Page 1)

A number of Decnis 600 units in use at customer locations have experienced power supply failures. The failures are caused by an electrical short in the transformer, which results in the power supply overheating.

The 30-36324-01 power supply is manufactured by ASTEC Corporation. The DC/DC converter component of the power supply undergoes hipot testing as part of the manufacturing process. This testing can result in "carbonization" of the transformer windings within the DC/DC converter, which eventually causes the failure. No system warning is generated by the DECNIS system. Therefore, the DECNIS 600 shuts down without prior notice. The failure can occur at any time after the product is placed in service.

Digital Product Safety has determined that the DECNIS 600 enclosure effectively contains the malfunction, and that the failures do not constitute a safety hazard.

FCO DNSBX-0001

PAGE 3 OF 4

INSTRUCTIONS ON HOW TO INSTALL THE DNSBX-0001 FCO

- 1. Refer to Chapter 11 of the "DECnis 600 Service Manual" (EK-A0543-IN) for instruction on how to remove and replace the parts needed for this FCO. Refer to Chapter 4 for testing the installed system.
- 2. Power down the system and disconnect power cord from wall outlet.
- 3. Attach the static protection equipment.
- 4. Remove the protective cover.
- 5. Loosen the screw and remove the power supply unit from the system.
- 6. Install EQ-01683-01 and reverse the preceding steps.
 - *** Before powering up the DECnis 600 make sure that all cards are seated correctly.
- 7. Power up the system.
 - *** If the system passes the power-up self test, and loads and runs the DECnis 600 software successfully, the FCO is complete.
- 8. Return the old power supply for upgrade.
- 9. Report this FCO activity on the LARS form in the "Fail Area/Module/FCO/Comments" column as follows: FCO DNSBX-0001. (See Page 4)

+							+	
								FCO DNSBX-0001
D	i	g	i	t	a	1		
				ĺ				PAGE 4 OF 4
+					- 		+	
								İ

LARS

	USA	APA	EUROPE
Activity -	0.011	11111	201012
(a)Contract	W	U	K
Warranty	W	U	W
(b)IN-DEC Contract	K	U	A
Non Contract/Non Warranty	F	F	F
(c)RTD/Off-site Agreement	F	U	F
Hardware Segment Code	111	111	111
Product Line	031/001	031/001	031/001
DEC Option	DNSB*	DNSB*	DNSB*
Option ID	X	N/A	N/A
Type of Call	M	M	M

Action Taken	D	D	I/V
Fail Area-Module-FCO-Comments	DNSBX-0001	DNSBX-0001	DNSBX-0001
Material Used	EQ-01683-01	EQ-01683-01	EQ-01683-01

If customer wants FS to provide Material and Labor and the "Event" is customer billable, FS should not use EQ kits but rather piece parts from stock.

Note: NO AUDIT TIME AUTHORIZED FOR THIS FCO log call using Activity 'K', Type of Call 'T', Action Taken 'M' and Product Line 031 or 001

FCO CHARGING INFORMATION									
 WARR <i>I</i>	ANTY/C	ONTRACT		NONWARRANTY/NONCONTRACT					
 ON-S]	ON-SITE OFF-SITE			ON-SITE		SITE	MATERIAL ONLY**		
TRAVEL/	EQ		EQ	 TRAVE			EQ	ORDER-ADMIN, HANDLING	
INSTALL	KIT	INSTALL	KIT	IINSTA	LL KIT	INSTALL	KIT	PKG,SHIPPING & EQ KIT	
 DEC 	DEC	 DEC 	DEC	 CUS 	 CUS* 	CUS	 CUS* 	 CUS* 	

^{*} FCO material (EQ Kits) will be provided at the prevailing cost-recovery prices.

⁽c) Labor ONLY reporting if customer should order EQ from DAS.

^{*} Used for Authorized FCO audits and multiple use EQs.

^{**} FCO material (EQ Kits) are available through the Digital Self-Maintenance Services Group on an exchange basis, unless otherwise specified in the FCO document.