_ FCO PMAG-DB-F001, Extremely slow performance w/o diag failure

DIGITAI			FC	0			CATI [I	EGORY F]	Y PAGE 1 OF 3				
FIELD (CHANGE	ORDER				NU	MBER: I	PMAG-DI	B-F001				
APPLICA All Tur PMAG-DF	ABILITY cbochar 3 graph	7: nnel sys nics opt	tems ot ion (Lo	her than w 3D) bui	the D lt pr	55000 Mo ior to 5	del 200 /24/91) that insta	will 1 lled in	nave a n them	a n.		
NOTE: This FCO is to be implemented on an "AS NEEDED" basis.													
PROBLEM & SYMPTOM: There will NOT be any diagnostic failure. The system will run EXTREMELY slow with pauses between each character printed. (Problem Statement continued on Page 2)													
SOLUTION: This "as needed" FCO will be issued so that Contract and Warranty customers with "old" boards that have exhibited problems can be upgraded to current rev. at no charge.													
QUICK CHECK: Check the serial number on the PMAG-DB graphics option. If built in ABO prior to 5/24/91 or if built in AYR prior to 5/12/91, the FCO is needed.													
PRE/CO-REQUISITE FCO: KN02-AA											HRS Irs.		
TOOL/TEST EQUIPMENT: N/A													
FCO PARTS INFORMATION													
FCO KI	r no.		DESCR	IPTION OF	CONT	ENTS		E(Q KIT V	/ARIA]	CION TV		
EQ-01611 FA-04944	L-01 <u>4</u> -01	54-201 FCO Doo	85-01 P cument	MAG-DB Option									
	FCO CHARGING INFORMATION												
WARRANTY/CONTRACT NONWARRANTY/NONCONTRACT													
ON-SITE OF			 SITE 	ON-SIT	Έ	OFF-	SITE	MATERIAL ONLY			ζ		
TRAVEL/ INSTALL	EQ KIT	 INSTALL	EQ KIT 	 TRAVEL/ INSTALL 	EQ KIT	 INSTALL	EQ NSTALL KIT 		RDER-ADMIN,HANDLIN KG,SHIPPING & EQ K				
DEC	DEC	DEC	DEC	CUS	CUS			CUS					
	APPROVALS												
CSSE Joe Amo	orelli	C; C;	S LOGIS arol Sa	TICS rasin			CS PRODUCT SAFETY Robert Brister						
CSSE MA	ANAGER		his doc	ument is	publis	shed	FCO REI	LEASE I	DATE				

John Leeds	on multiple media including	30 May 1991
	hardcopy, Customer Services	
MICROMEDIA	Microfiche Libraries,	FCO REVISION
Diane MacDonald	Customer Services CD-ROM and	Α
	MDS Microfiche Libraries.	
POPULATION		PARTS AVAILABILITY
1,000		June, 1991
	İİ	

+							 	-+					
										FCO	PM.	AG-DI	B-F001
	d	i	g	i	t	a	1						
										PAGE	2	OF	3
+							 	-+					

Problem Statement (Continued from Page 1)

A quantity of approximately 1,000 Low 3D modules will have been built and delivered before implementation of an ECO which isolates DMA errors received by the N10 to the 3D option module. Without this change, the N10 could respond to any DMA error signal which was generated by any other DMA engine on the system. In such a case, the N10 would hang. This presents an immediate problem on 3MIN due to DMA being used in the baseboard I/O. This ECO will be implemented prior to 3MIN availability. The affected customers would be those moving their 3D options from a 3MAX to a 3MIN or any other Turbochannel system.

* * * * * * * * * * * * * * * * * * * *								
* CAUTION	*							
*	*							
* Observe proper ESD procedures while installing the FCO.	*							
*	*							
******	* * *							

Installation of this FCO would be done in the same manner as replacing any Turbochannel option. The following procedure can be used.

- 1. Shutdown the system software. (If necessary follow the instructions that came with the workstation software).
- 2. Turn off the system by pressing the " 0 " on the on/off switch located on the back of the unit.
- 3. Remove the cover from the unit.
- 4. Determine which slot the option will occupy. If necessary remove the existing Turbochannel option or rear cover plate(s).
- 5. Position the option module so it is in parallel to the bottom of the system unit, with the Turbochannel connector facing down.
- 6. Move the option module cable connector through the option slot opening in the back of the system unit.

- 7. Firmly push the Turbochannel connector into its mate on the Turbochannel bus.
- 8. Assure proper alignment with the support posts. Insert the support post screws and tighten until the option is held securely in place.
- 9. Replace cover on the system unit and connect cable to the Turbochannel option.
- 10. Turn on the system unit and monitor.
- 11. Report the FCO activity on the LARS form in the "module/fail/ area/FCO" column as per example on Page 3.



\\PMAG-DB \\PMAG