$_$ FCO TA91-S001, Connector can be broken on the 60HZ power supply.

DIGITAL	FCO		DRY PAGE 1		
		[S]	OF 4		
FIELD CHANGE (DRDER	NUMBER: TAS	91-S001		
TA91X-BA, TU91 ECO TA91-SH003	This "S" coded FCO mus -BA, TU91-DA and TU91U-D and changes the revision CO1" and TU91-DA/EA to " th this FCO.	DA options. This FCO on of the TA91-AA/BA) incorporates to "D01",		
PROBLEM & SYMPTOM: It is possible to break connector J11 on the 60Hz power supply. Breakage of the connector can occur if the connector cable is pulled on without releasing the connector locks. If this occurs, a potential safety hazard exists if the detached (broken) cable, which carries 208vac, makes contact with the power supply frame or with service personnel.					
 SOLUTION: Retr 	cofit the power supply us	sing a pair of plast:	ic connector braces.		
· 1	The opening in the power pair of plastic connecto		:		
 PRE/CO-REQUISI 	TTE FCO: None		MTTI HRS .6		
TOOL/TEST EQUI	IPMENT: None				
 FCO PARTS INFORMATION					
FCO KIT NO.	DESCRIPTION OF CONTENTS				
 EQ-01667-01					
 FA-05004-01	FA Document				
FCO CHARGING INFORMATION (See Last Page)					
<u> </u>					
APPROVALS					
TECH. ENGINEER		DS LOGISTICS Bob Senfleben	DS PRODUCT SAFETY Robert Brister		
 MICROMEDIA	PARTS AVAILABILITY	FCO REVISION	FCO RELEASE DATE		

+		+	
			FCO TA91-S001
d i	g i t	a 1	
j j	i i i		PAGE 2 OF 4
+		+	

Customer Statement: This FCO is designed to prevent a possible safety hazard to service personnel. No safety hazard exists unless connector J11 on the TA91/TU91 60HZ power supply is broken.

Installation Procedure:

- 1) Verify that you have the connector braces listed on Page 1 of this document.
- 2) Refer to Figure 1 for locations and connector brace positioning.
- 3) Unload all tape cartridges in the drive.
- 4) Turn the AC breaker (1) to the OFF position for the power supply to be upgraded with the connector braces.
- 5) Gain access to connector J11 and pull out the cable connector attached to it.
- 6) Install a brace (2) above and below connector J11 as shown in Figure 1. The braces should "snap" into place.
- 7) Reconnect the cable removed in Step 5.
- 8) Turn the AC circuit breaker (1) to ON for the power supply which has been upgraded.
- 9) Repeat Steps 4 through 8 for all affected power supplies in the tape drive.
- 10) Report this FCO activity on the LARS form in the "Fail Area/Module/FCO/Comments" column as follows: FCO TA91-S001 (See LARS example on the next page)



FCO TA91-S001

PAGE 3 OF 4

FCO TA91-S001

PAGE 4 OF 4

LARS

	USA	GIA	EUROPE
Activity -			
(a)Contract	W	U	K
Warranty	W	U	W
(b)IN-DEC Contract	K	Ū	А
Non Contract/Non Warra	nty W	W	F
(c)RTD/Off-site Agreement	W	W	F
Hardware Segment Code	111	111	111
Product Line	031		031
DEC Option	TA91/TU91	TA91/TU91	TA91/TU91
Option ID	X	N/A	N/A
Type of Call	M	M	M
Action Taken	D	D	I or V
Fail Area-Module-FCO-			
Comments	ΓA91-S001	TA91-S001	TA91-S001
Material Used	EQ-01667-01	EQ-01667-01	EQ-01667-01

- (a) Warranty Optimum, Warranty Standard and Warranty Basic (on-site)
 Agreements; * Note material (only) free of charge for all customers.
- (b) Applies to IN-DEC Area Only
- (c) RTD=Return to Digital or Off-site Agreements; If Field Engineer On-site, use Activity Code "F".

WARRANTY/CONTRACT		NONWARRANTY/NONCONTRACT						
ON-SITE OFF-SITE		 ON-SITE		OFF-SITE		 MATERIAL ONLY		
 TRAVEL/ INSTALL	EQ KIT	 INSTALL	EQ KIT	 TRAVEL/ INSTALL	EQ	 INSTALL	EQ KIT	ORDER-ADMIN, HANDLING PKG, SHIPPING & EO KIT
 DEC	DEC	DEC	DEC	 CUS	DEC	 DEC	DEC	DEC

\\FCO_DOCS \\EQ-01667