-,-,-,-,-,-	Leve	l of Urgency	Page_1_
	FCO	++  I   ++	Of_3_
FIELD CHANGE ORDI	 ER	Number: TK50-	I002
	TK50 Tape drives below Reion is on a label attached		he drive.)
O	ntermittent load/unload pr perator errors; inability nduced failures.		
Quick Check:	nstalled drive is Revision	El or above.	
Compatibility/Prerequisite FCO: N/A		Est. Time	to Install:
Special Tools or Te	est Equipment: Field Servi	ce Tool Kit	
	FCO Parts Infor	mation	
Order by (	Quantity: Part Numb	er: Descri	ption:
EQ-01475-01	1	TK50 d	rive 1 or higher)
FA-04764-01	1		ntation
IQ Kit Variation Sys	stem/Option Applic:	N/A	
	Approvals		
CSSE Engineer Bob Steere	F.S. Product Safety   Steve Caccia	F.S. Logis	tics
CSSE Manager Steve Dail		es Affected Poper	ulation:
MicroMedia Pub.	_	Initial Kitt	ing:
Ray LeBlanc	VAXnotes _  STARS	26,500 	
Revision: A		Hardcopy Pub	lication:
FCO Release Date	_	   Parts Availa	bility:

\_\_\_\_\_ FCO TK50-I002

The minimum shippable level of the TK50 Tape Drive will be E1 as of July 15, 1987 from all Field Service repair locations. FSL repair locations will install the new receiver; new idler tape guide; new link mechanism; new bezel and update the drive module to include the new drive microcode. The FCO kit will contain a drive having all of these changes installed, plus a warning label on the handle.

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*

- \* The TK50 contains electrostatic discharge sensitive devices.\*
- \* The use of the Velostat kit is essential when replacing

- 1. Perform normal system shutdown procedures. REFER TO APPROPRIATE SYSTEM MANUALS FOR SYSTEM INVOLVED.
- 2. Power down system.
- 3. Remove covers and panels to gain access to the TK50. Remove power and signal cables from drive. Remove drive from mounting slot.
- 4. Using reverse procedure, replace removed drive with drive from kit provided. Make sure the Revision of the drive provided is Revision El or higher. The Revision is noted on a label at the back of the drive.
- 5. Replace all covers and panels.
- 6. Observe for normal power up diagnostic completion.
  Refer to paragraph 4.4.1.7 and 4.4.1.8, page 4-12 in the TK50
  TK50 Tape Drive Subsystem Manual, # EK-OTK50-TM.
- 7. Run one pass of TK50 MDM diagnostic or applicable 11 system Data Reliability Diagnostic before returning to customer.
- 8. Complete LARS form as per attached sample. Return drive to Logistics in shipping container as soon as possible.
- 9. The repair tag should be marked "FCO ONLY" in the comments area.

Local Field Service offices must insure that this FCO/drive replacement is conducted by TRAINED PERSONNEL ONLY! The installing F.E. should make available to customer personnel the video entitled "TK50 User Familiarization" during the installation of this FCO/updated drive. A copy of this video will be shipped to each Field Support Manager prior to July 1, 1987. It is also available from Ed. Services. The order number is EY-2898E-U1-0001.

	FCO TK50-I002
d i g i t a 1	PAGE 3 OF 3
- - - - -	
	_

LARS

	USA	GIA	EUROPE
Activity -			
Contract and Warranty	W	U	Y
Non Contract/Non Warranty	F	F	F
DEC Option	TK50	TK50	TK50
Type of Call	M	M	M
Action Taken	D	D	I
Fail Area-Module-FCO-Comments	TK50-I002	TK50-I002	TK50-I002
Material Used	EO-01475-01	EO-01475-01	EO-01475-01

\^ TK50 \\TK50 \\STEERE \\1987 \\JUN \\FCO\_DOCS