

DIGITAL

FCO

CATEGORY [0]

PAGE 1 of 13

FIELD CHANGE ORDER -

NUMBER: KN02-AA-0001

APPLICABILITY: All Systems containing KN02-AA CPU's manufactured before 27-AUG-1990 including but not limited to the following:

PM361-BD PM361-BE PM361-BG PM361-BH PM361-BK PM361-BL PM361-MD PM369-PZ
 PM361-ME PM361-MG PM361-MH PM361-MK PM361-ML PM362-BK PM362-BL PM371-BY
 PM362-DK PM362-DL PM362-MK PM362-ML PM362-PK PM362-PL PM369-PY PM372-BY

PROBLEM & SYMPTOM:

1. Firmware Spec too Complex for the Open Systems Environment
2. TURBOchannel Modules Lift Out of System I/O Connectors
3. Excessive Resistance Build up in the 5V Power Connector

SOLUTION: 1. Replace (4) socketed ROM's on system module and (1) socketed ROM on each TURBOchannel option present.
 2. Add six standoffs to system module which the options bolt to.
 3. Clean 5V and GND connectors with a "Gold-Wipe" towelette containing PPE.

QUICK CHECK: If the firmware revision displayed during power-up is below 5.3c install the FCO.

PRE/CO-REQUISITE FCO: None

MTTI 1.5 hr

TOOL/TEST EQUIPMENT:

ROM Extraction Tool: 29-28497-01 (included in EQ Kit)
 ESD Kit: 29-26246-00 or equivalent

FCO PARTS INFORMATION

FCO KIT NO.	DESCRIPTION OF CONTENTS	EQ KIT VARIATION APPLICABILITY
EQ-01589-01	Quantity Part Number Description (See Page 6 for Contents of EQ Kit)	None
FA-04919-01	1 FA Document	

FCO CHARGING INFORMATION

WARRANTY/CONTRACT				NONWARRANTY/NONCONTRACT				
ON-SITE		OFF-SITE		ON-SITE		OFF-SITE		MATERIAL ONLY
TRAVEL/ INSTALL	EQ KIT	INSTALL	EQ KIT	TRAVEL/ INSTALL	EQ KIT	INSTALL	EQ KIT	ORDER-ADMIN, HANDLING PKG, SHIPPING & EQ KIT
DEC	DEC	DEC	DEC	CUS	CUS	CUS	CUS	CUS

APPROVALS

CSSE ENG
 Dave Oliver

FSHQ LOGISTICS
 Carol Sarasin

FS PRODUCT SAFETY
 Robert Brister

CSSE MANAGER Jay Nagro	FS. MICROFICHE LIBRARIES	FCO RELEASE DATE 27 Aug 1990
MICROMEDIA Diane MacDonald	VAXDOC EP-CSVDC-LB VAX/PDP EP-CSMST-LB	FCO REVISION A
POPULATION 2,557	VAX Notes STARS	PARTS AVAILABILITY August, 1990

```

- - - - -
| d | i | g | i | t | a | l |
| - | - | - | - | - | - | - |

```

FCO KN02-AA-0001
PAGE 2 OF 13

KNO2-AA-00001 FCO INSTALLATION PROCEDURE

```

*****
*                               ** IMPORTANT **                               *
*
*   The purpose of this document is to provide the engineer                 *
*   with an overview of the procedure used to install                       *
*   the FCO.                                                                  *
*
*   The installation is described in detail in the                          *
*   DECstation 5000 FCO Upgrade Manual (EK-FSFCO-RO)                       *
*   included in the EQ Kit.                                                  *
*
*****

```

TABLE OF CONTENTS

Overview.....Page 3

FCO Procedure.....Page 4

Firmware Changes.....Page 5

Materials.....Page 6

ROM Locations.....Page 7
Revision Control.....Page 8
Documentation.....Page 9
LARS Information.....Page 10
Scrap Material.....Page 11
Technical Background.....Page 12

_	_	_	_	_	_	_
d	i	g	i	t	a	l
_	_	_	_	_	_	_

FCO KN02AA-O001

PAGE 3 OF 13

OVERVIEW

The primary reason for the FCO is to implement a new firmware architecture into the DECstation 5000/Model 200 workstation and DECsystem 5000/Model 200 server. The firmware fix involves replacing four socketed ROMs on the system module and one socketed ROM on each TURBOChannel option present in the system. While on site, service personnel will perform two additional tasks:

- o Add six standoffs to the system enclosure which the TURBOChannel modules will bolt to. This will prevent modules from lifting out the system I/O connectors.
- o Clean the 5V power connectors with a "Gold-Wipe". A Gold-Wipe is a towelette treated with PPE (Polyphenyl Ether), an anti-oxidant/lubricant. This will extend the life of the power connector.

_	_	_	_	_	_	_
d	i	g	i	t	a	l
_	_	_	_	_	_	_

FCO KN02-AA-O001

PAGE 4 OF 13

The purpose of this section is to provide the engineer with an overview of the procedure used to install the FCO. The installation is described in detail in the DECstation 5000 FCO Upgrade Manual (EK-FSFCO-RO) included in the EQ Kit.

1. Determine if a system is a candidate for the FCO. If the firmware revision displayed during power-up is below 5.3c install the FCO.
2. From the console, display and record all System Environmental Variables contained in the current firmware. This information will be needed later (see step 9) to reset the Environmental Variables.
3. Remove cover and clean 5V Power connectors with a Gold-Wipe. Place the used Gold-Wipe in the zip lock bag provided, for disposal.
4. Add standoffs if needed. Bolt the six standoffs into pre-drilled and tapped holes in the system module. Use the machine screws to secure each TURBOChannel option.
5. Remove ALL 4 ROMs from the base system module plus ALL ROMs in the TURBOChannel option modules. (For ease of installation you may need to remove the power supply)
6. Install the 2 base system ROMs (High, Low) and verify with power-up selftest. The diagnostic LED's on the back of the system will blink on and off as self test runs. If the LEDs stay lit for more than 30 seconds self test has failed.
7. Replace the two remaining base system ROMs (NI, SCSI) and any ROMs in the TURBOChannel options modules. Use power-up self test to verify the total system is operational.
8. Apply new revision labels to all updated modules.
9. Reset the environmental variables including the boot path. (use the information recorded in step 2)
10. Verify that the system boots Ultrix.
11. Leave customer documentation packet on site.

```

- - - - -
| | | | |
|d|i|g|i|t|a|l|
| - - - - -
```

FIRMWARE CHANGES

This new Firmware incorporates major changes to the console and diagnostic commands. If you have experience working with the DECstation 5000/Model 200 workstation or DECsystem 5000/Model 200 server you will find the new console and diagnostics radically different. The console has adopted the industry standard UNIX - C language look and feel.

```
*****
*                               ** IMPORTANT **                               *
*                               *                               *
* It is important for the service engineer to understand how *
* the console has changed. For example a new command string is *
* used to define the boot path. *
*                               *
*****
```

As an educational aid we have included a copy of the revised DECstation 5000/Model 200 Maintenance Guide in the EQ kit. This manual is for service engineers. Please take it with you when you leave the site and use it to familiarize yourselves with the new interface. This document describes in detail the usage of the new console and diagnostic commands.

d	i	g	i	t	a	l	

FCO KN02-AA-0001

PAGE 6 OF 13

MATERIALS

This section contains a description of the material contained in the EQ kit.

FCO KIT CONTENTS

Table #1

Part Number	Description	QTY
(70-28331-01, Pre-packaged FCO Parts as listed below)		
70-28330-01	ROM Assembly	2*
70-28332-01	Gold-Wipe Assembly	1 ...with zip lock bag...
70-28329-01	Screw/Standoffs	1
36-34442-01	REV Labels	1
29-28497-01	ROM Extraction Tool	1 ...used on 2da only...
EK-FSFCO-DK	Service Doc Kit	1
EK-CUFCO-DK	Customer Doc Kit	1

Note #1: (* Two sets of ROMs)

Each kit contains two complete sets of ROMs. Customers may have system configurations with duplicate options. There are also spare ROMs in the event of a problem during installation.

```

*****
*                               ** CAUTION **                               *
*                               *                                           *
* The ROMs contained in the EQ Kit are sensitive to electrostatic *
* discharge. Use ESD kit (29-26246-00) or equivalent during the *
* ROM installation. Following standard ESD procedures will *
* minimize the possibility of damaging system components. *
*                               *                                           *
*****

```

```

|_|_|_|_|_|_|_|_|_|
|d|i|g|i|t|a|l|
|_|_|_|_|_|_|_|_|_|

```

FCO KN02-AA-0001

PAGE 7 OF 13

ROM LOCATIONS

ROM CROSS REFERENCE TABLE

Table #2

ROM Part Number	Description	OPTION PART #	MODULE PART #	Board Location
23-096E8-00	Base ROM High	KN02-AA	54-19811-01	E17
23-097E8-00	Base ROM Low	KN02-AA	54-19811-01	E61

23-578E6-00*	NI ROM	KN02-AA	54-19811-01	E188
23-579E6-00**	SCSI ROM	KN02-AA	54-19811-01	E220
23-241E7-00	CFB ROM	PMAG-B	54-19815-01	E30
23-185E9-00	2DA ROM	PMAG-C	54-20314-01	E28
23-578E6-00*	NI ROM	PMAD-A	54-19874-01	E3
23-579E6-00**	SCSI ROM	PMAZ-A	54-19876-01	E15

Example #1

Install the ROM labeled with part number "23-096E8-00" in location E17 on the KN02-AA system module. (See the FCO Installation Guide for diagrams)

Example #2

Install the ROM labeled with part number "23-241E7-00" in location E30 on the 54-19815-01 board. (See the FCO Installation Guide for diagrams)

Note #2: (Duplicate Part Number)

- * The same NI diagnostic ROM is used on both the base KN02-AA and the PMAD-A module.
- ** The same SCSI diagnostic ROM is used on both the base KN02-AA and the PMAZ-A module.

-	-	-	-	-	-	-	-
	d		i		g		i
	t		a		l		
	-		-		-		-

FCO KN02-AA-0001
PAGE 8 OF 13

REVISION CONTROL

This kit contains a sheet of Revision Labels. After each module is upgraded place a new Revision Label over the old one.

*
* The FCO Installation Guide (EK-FSFCO-RO), contained in *
* the EQ Kit, has diagrams of each module which show the *

* location of the Revision label.
 *

ROM REVISION TABLE

Table #3

Module Part Number	Option Part Number	Description	Current REV	FCO Rev
54-19811-01	KN02-AA	System Module	B09,C09	D09,D09*
54-19815-01	PMAG-B	CFB	A06,B06,B07	C06,D06,D07
54-20314-01	PMAG-C	2DA	D03,E03	F03,H03
54-19874-01	PMAD-A	NI	A06,A07,B07	C06,C07,D07
54-19876-01	PMAZ-A	SCSI	A05,A06	B05,B06

Example #3

If you upgrade a Rev "B06" CFB Module place a new Rev "D06" sticker over the old revision label of the 54-19815-01

Note #3: (* Duplicate Revision)

* Yes this is correct; the only difference between the KNO2-AA Rev "B09" and Rev "C09" was the firmware. When the new code is added to either revision of the system module, the new revision becomes "D09".

```

  _ _ _ _ _
 | | | | |
 |d|i|g|i|t|a|l|
 | _ _ _ _ _

```

```

FCO KN02-AA-0001

PAGE 9 OF 13

```

DOCUMENTATION

EQ KIT DOCUMENTATION

Table #4

Part Number	Description	Qty of Manuals	Intended Audience
EK-FSFCO-DK	Service Documentation	3	Services Engineer
EK-CUFCO-DK	Customer Documentation	5	Customer

Table #5

Part Number	Description
EK-FSFCO-RO	DECstation 5000 FCO Upgrade Manual
EK-370AA-MG	Maintenance Guide
EK-FSFCO-RC	Console Command Reference Card

CUFCO-DK CUSTOMER DOCUMENTATION KIT CONTENTS

Table #6

Part Number	Description
EK-CUFCO-CC	Console Commands
EK-CUFCO-CL	Read Me First
EK-367AA-IC	Installation Card
EK-FCOIN-UG	Hardware Installation Guide Update
EK-FSFCO-WS	Ultrix Boot Commnads

```

*****
*
*   Leave the Customer Documentation Kit with the customer   *
*
*****
    
```

```

- - - - -
|d|i|g|i|t|a|l|
- - - - -
    
```

FCO KN02-AA-0001

PAGE 10 OF 13

LARS INFORMATION

CATEGORY O	USA	GIA	EUROPE
Activity -			
(a) Contract and Warranty	W	U	W
In-DEC Contract	W	Country Specific	W
Hardware Segment Code	111	111	111
RTD/Off-site Agreement	(b)	(b)	(b)
Servicenter			

DEC Option	KN02-AA	KN02-AA	KN02-AA
Type of Call	M	M	M
Action Taken	D	D	D
Fail Area-Module-FCO-Comments	KN02-AA-O001	KN02-AA-O001	KN02-AA-O001
Material Used	EQ-01589-01	EQ-01589-01	EQ-01589-01

- (a) First revenue ship of the DECstation 5000/Model 200 and the DECsystem 5000/Model 200 occurred in April 1990. Systems shipped after September 1, 1990, have been built with the new firmware. All systems shipped within this time frame, whether sold with List Warranty or Standard Warranty are covered by the FCO.
- (b) Due to the nature of this FCO, CSSE does not recommend it be performed in the Servicenter. To verify that the firmware has been properly installed the customer must bring the entire system including the monitor and external mass storage into the servicenter.

Transportation and storage of bulky systems can be burdensome to both the customer and the Servicenter and can cause significant customer satisfaction problems. This is only a recommendation, the final decision is a local one.

```

- - - - -
| | | | | | | |
|d|i|g|i|t|a|l|
|_|_|_|_|_|_|_|

```

FCO KN02AA-O001

PAGE 11 OF 13

SCRAP MATERIAL

Upon successful completion of the FCO please remove the old ROMs from the customer site and destroy them. This will prevent the old ROMs from being accidentally installed in a system. Make sure the system has booted ULTRIX and is fully operational before destroying the ROMs. Please follow local policies and procedures for the disposal of scrap material.

The EQ kit contains two sets of new ROMs. After successful installation of the FCO, Customer Service Engineers may find them selves with unused ROMs. The disposition of this material is left up to the engineer. EQ kits are an expensed item there is no logistics credit for returned ROMs.

_	_	_	_	_	_	_
d	i	g	i	t	a	l
_	_	_	_	_	_	_

FCO KN02-AA-0001

PAGE 12 OF 13

TECHNICAL BACKGROUND

PROBLEM 1

"Firmware Spec too Complex for the Open Systems Environment"

A review of the DECstation 5000/Model 200 firmware has revealed that the current firmware implementation is unnecessarily complex and cumbersome to implement.

SOLUTION:

The firmware has been redesigned. It is now substantially easier for both Digital and Third Party TURBOChannel hardware developers to understand and implement.

FCO IMPLEMENTATION:

Replace four socketed ROMs on the system module and one socketed ROM on each of the TURBOChannel options present in the system.

PROBLEM 2

"TURBOChannel Modules Lift Out of System I/O Connectors"

DECStandard 102 ESS testing, of the DECstation 5000/Model 200 with the 2DA graphics accelerator and 3D graphics modules, revealed that these TURBOChannel modules will lift out of the system I/O connectors. 2DA External Field Test also identified this as a problem.

SOLUTION:

Add Standoffs to the system enclosure.

FCO IMPLEMENTATION:

Bolt six standoffs to the system enclosure. Then use a machine screw to attach all the TURBOChannel Module to the standoff. The CPU, enclosure and TURBOChannel modules are all pre-drilled and tapped to accept standoffs and machine screws.

_	_	_	_	_	_	_
d	i	g	i	t	a	l
_	_	_	_	_	_	_

FCO KN02-AA-0001

PAGE 13 OF 13

PROBLEM 3

"Excessive Resistance Build up in the 5V Power Connector"

Power supply life testing revealed that over time excessive contact resistance will build up on the 5V connectors. This resistance causes excessive heat build up and can result in a voltage drop across the power connector, sufficient to impact reliable system operation.

Corporate safety has reviewed this problem and has determined that there are no safety issues.

SOLUTION:

Apply PPE An anti-oxidant/lubricant to the 5V connectors of the power supply.

FCO IMPLEMENTATION:

Clean the power Connectors with a "Gold-Wipe". A Gold-Wipe is a towelette treated with PPE. They are used widely in both Manufacturing and Customer Service. Place the used Gold-Wipe in the zip lock bag provided, for disposal.

\\DS5000
\\3MAX
\\3max
\\ds5000
\\DECstation

\\^ KN02
\\KN02
\\KN02-AA
\\OLIVER
\\1990
\\AUG
\\FCO_DOCS