


Temperature/ Humidity Monitor Unit



1. Power indicator: Run
2. Button: Switch temperature to Humidity. (Auto switch to temperature after 4 seconds)
3. T/C: Temperature indicator
4. H/%: Humidity indicator
5. Digital display for ampere (A)
6. RJ11 port: Temperature/ Humidity sensor port
7. Fuse
8. Power Input: IEC C14

temperature&humidity sensor



Item	performance parameter	
Working voltage	220V~250V 50~60/Hz	
Temperature monitor	Range:	-40°C-99°C;
	Resolution	0.1°C;
	Error	0.5°C;
	Response time	4S
Humidity monitor	Range:	0-100%;
	Resolution	0.1%;
	Error	5%;
	Response time	4S
Size & Specifications	Size (LxWxH)	482.6x68x44.4mm;
	Mounting way	19" bracket mounted
	Color	Black (RAL 9004)
Power consume	About1.0W;	
Working environment	Temperature	0°C-100°C;
	Relative humidity	0-100%;