

<pre>  _ _ _ _ _ _ _ _   d i g i t a l   _ _ _ _ _ _ _ _  </pre>	FCO TA81	Level of Urgency +---+  I  +---+	Page_1__ Of_5_
--	----------	---	-------------------

FIELD CHANGE ORDER

Number: TA81-I001

## Applicability:

Rework all TA81 Transports with STI Controller Modules at (Vendor) P/N 77042145 and below. All TA81 Option Revision Level A1, B1 and C1. This FCO incorporates ECO's TA81-SH002 and TA81-SH003.

## Problem/Symptom:

"Blocks Lost" or "Position Lost" error on Backup/Verify operation during VMS Backup. Acknowledge not set at start of transfer.

## Quick Check:

ROM in location G2 on STI Interface board at STI0908-1 (P/N 77028485)

Compatibility/Prerequisite FCO: N/A

Est. Time to Install:
.75 Hrs

Special Tools or Test Equipment: N/A

## FCO Parts Information

Order by FCO Kit#:	Quantity:	Part Number:	Description:
EQ-01443-01	1	29-26209	CDC FCO #52013
FA-04729-01	1		FCO Document

EQ Kit Variation System/Option Applic: N/A

## Approvals

CSSE Engineer Frank Raffa	F.S. Product Safety Steve Caccia	F.S. Logistics Ed Duggan
------------------------------	-------------------------------------	-----------------------------

CSSE Manager Steve Dail	F.S. Microfiche Libraries EP-FSNVX-LB VAX	Affected Population: 400
----------------------------	--	-----------------------------

ESD&P Micropub. Ray LeBlanc	VAXnotes	Initial Kitting: 400
--------------------------------	----------	-------------------------



8. Remove the ROM at location G4 and replace it with ROM P/N 77028494 (See Figure 1).
9. Remove the ROM at location G6 and replace it with ROM P/N 77028514 (See Figure 1).

```

|_|_|_|_|_|_|_|_|
|d|i|g|i|t|a|l|
|_|_|_|_|_|_|_|_|

```

FCO TA81-I001

PAGE 3 OF 5

10. Change the Module part number to (Vendor) 77042146.
11. Set on switches 2 and 1 on the Revision Dip Switch behind the formatter boards.
12. Reverse the steps 3 through 1 of the Interface Module Removal Procedure (See page 128 of the Maintenance Guide).
11. Return the TA81 tape deck to the operating position.
12. Return power to the TA81 by reversing the sequence in step 4.
13. To verify the TA81 is functioning properly. Perform the Operator Test 01. Complete one full pass of ILEXER.

```

*****
*                                     NOTE   (US AREA ONLY)                               *
*                                                                                             *
* Due to the extreme shortages,                                                                 *
* you are requested to return the Digital Equipment Corporation                               *
* old ROMS to:                                                                                   *
*                                                                                   333 South Street                               *
*                                                                                   Shrewsbury, MA 01545                               *
*                                                                                   SHR1-4/D16  ATTN: Frank Raffa                               *
*****

```

14. Change the Serial number tag to Revision C2.
15. Fill out Site Management Guide to reflect this FCO.
16. Report FCO activity on the LARS form as indicated on page 5.

-	-	-	-	-	-	-	-
d	i	g	i	t	a	l	
-	-	-	-	-	-	-	-

FCO TA81-I001

PAGE 4 OF 5

Figure 1

-	-	-	-	-	-	-	-
d	i	g	i	t	a	l	
-	-	-	-	-	-	-	-

FCO TA81-I001

PAGE 5 OF 5

LARS

Activity	DEC Option	Type of Call	Action Taken	FCO # Comments	Material Used
----------	---------------	--------------------	-----------------	-------------------	------------------

\*\*\*\*\*  
For Contract and Warrant Customers U.S. and G.I.A.

W	TA81	M	D	TA81-I001	EQ-01443-01
---	------	---	---	-----------	-------------

\*\*\*\*\*  
For Per Call Customers U.S., G.I.A and Europe

F	TA81	M	D	TA81-I001	EQ-01443-01
---	------	---	---	-----------	-------------

\*\*\*\*\*  
For Contract and Warranty Customers Europe

Y	TA81	M	D	TA81-I001	EQ-01443-01
---	------	---	---	-----------	-------------

\*\*\*\*\*  
\  
^ TA81  
\  
\  
TA81  
\  
\  
RAFFA  
\  
\  
1986  
\  
\  
OCT  
\  
\  
FCO\_DOCS