*** NOTE ***

Pages 3 thru 82 of FCO LPS40-R001 were especially prepared using the VAX DOCUMENT generic markup system. ASCII files for these pages, are not available. Additionally, these pages contain illustrations that are critical to the FCO. Please refer to to the hardcopy document (FA-04826-01) or your FCO/DEC-O-LOG microfiche titled LPS32 TO LXYXX (ES-LPS32-TI-S) in your MDS library.

DIGITAL FCO	LEVEL OF		
	URGENCY	PAGE 1	
		OF 82	
	[R]		
FIELD CHANGE ORDER	NUMBER: LPS40-R001		
APPLIC: FCO LPS40-I001 Will upgrade all field units of the LPS40 to revision level of B1. At the time of issue all field units will be at revision level of A1. See page 2 for more information.			
This revised FCO supersedes the original released 20 July 1988. It has been revised to include additional corrections for three hole paper jamming. Some procedures have been clarified and new part numbers added.			
PROB/SYMPT: The PrintServer 40 availability to customer has been severely reduced due to variety of problems affecting rate of jams and print quality. Symptoms include jamming, dirty printer, and print quality degradation.			
QCK CK: The FCO is called for in all cases where the revision level of LNO2, FDS, and LCIT are BELOW revision B1 as verified by barcode label.			
COMPATIB/PREREQ: N/A	EST INST 6.0 hou		
TOOLS/TEST EQUIP: See section "About This FCO" after the Table of Contents in the FCO document, for the required tools needed to complete this FCO.			

FCO PARTS INFORMATION

CONTENTS

DESCRIPTION

kit #1

kit #2

PART NUMBER

29-27219-01

29-27220-01

ORDER BY

FCO KIT #

EQ-01526-03

QUANTITY

1

1

FA-04826-01 1		FCO Document		
EQ KIT VARIATION/SYS-OPT APPLICABILITY: None				
APPROVALS				
CSSE ENGINEER John Parent	F.S. PRODUCT SAFETY Hank Aaron 	F.S. LOGISTICS Ed Duggan		
RESPON. CSSE MANAGER Ron Francoeur	F.S. MICROFICHE LIBS EP-FSP11-LB PDP11	AFFECTED POPULATION 1,300		
MICROMEDIA PUBLISHING Ray LeBlanc 	EP-FSNVX-LB VAX EP-FSPD8-LB PDP8 EP-FSLCG-LB LCG	INITIAL KITTING 1,300		
REVISION B 	 VAXnotes STARS	HARDCOPY PUBLICATION 1,300		
FCO RELEASE DATE 30 September 1988		PARTS AVAILABILITY July 88		

	FCO LPS40-R001
d i g i t a l	PAGE 2 OF 82
_ _ _ _	

This includes all units below serial RI802001368 That have not been ECO'd in manufacturing. This FCO implements 14 ECOs that are implemented in manufacturing. ECO numbers are listed below

29-26613-ML001	29-26606-ML001	29-26604-ML001
29-26595-ML001	29-25851-ML001	29-25891-ML001
29-25895-ML001	29-26345-ML001	29-26346-ML001
29-25847-ML001	29-25854-ML001	29-25875-ML001
29-25850-MI ₂ 001	29-25911-MI ₂ 001	

LARS

	USA	GIA	EUROPE
Activity -			
Contract and Warranty	W	U	Y
Non Contract/Non Warranty	F	U	F
DEC Option	LPS40	LPS40	LPS40
Type of Call	M	M	M
Action Taken	D	D	I
Fail Area-Module-FCO-Comments	LPS40-R001	LPS40-R001	LPS40-R001

EQ-01526-03 EQ-01526-03 EQ-01526-03

\^ LPS40 \\LPS40

\\LPS40-R001

\\PARENT

\\1988

\\SEP

\\FCO_DOCS