

DIGITAL FCO CATEGORY PAGE 1  
[I] OF 2

FIELD CHANGE ORDER NUMBER: KA655-I001

APPLICABILITY:

This FCO kit is to upgrade Field Service stockroom inventory of the M7625-AA/BA module from revision B1 to C1.

PROBLEM & SYMPTOM:

M7625-AA is revision B1 (ECO #M7625-TW003)

SOLUTION:

If M7625-AA/BA is at revision B1, replace with module from this kit and return revision B1 module for credit.

QUICK CHECK:

Verify module handle for revision C1.

PRE/COREQUISITE FCO:

MTTI HRS

N/A

N/A

TOOL/TEST EQUIPMENT:

N/A

FCO PARTS INFORMATION

FCO KIT NO.	DESCRIPTION OF CONTENTS	EQ KIT VARIATION APPLICABILITY
EQ-01614-01	M7625-AA, Revision C1	
EQ-01614-02	M7625-BA, Revision C1	
FA-04947-01	FCO Document	

FCO CHARGING INFORMATION

WARRANTY/CONTRACT

NONWARRANTY/NONCONTRACT

ON-SITE

OFF-SITE

ON-SITE

OFF-SITE

MATERIAL ONLY

TRAVEL/ INSTALL	EQ KIT	INSTALL	EQ KIT	TRAVEL/ INSTALL	EQ KIT	INSTALL	EQ KIT	ORDER-ADMIN, HANDLING PKG, SHIPPING & EQ KIT
--------------------	-----------	---------	-----------	--------------------	-----------	---------	-----------	---

DEC	DEC	DEC	DEC	CUS	CUS	CUS	CUS	CUS
-----	-----	-----	-----	-----	-----	-----	-----	-----

APPROVALS

CSSE Lou Poulin	FSHQ LOGISTICS Barry Weinstein	FS PRODUCT SAFETY Robert Brister
--------------------	-----------------------------------	-------------------------------------

CSSE MANAGER Larry Moore	This document is published on multiple media including hardcopy, Customer Services	FCO RELEASE DATE 10 June 1991
MICROMEDIA Diane MacDonald	Microfiche Libraries, Customer Services CD-ROM and MDS Microfiche Libraries.	FCO REVISION A
POPULATION 1,015	This document is also avail- able via TIMA.	PARTS AVAILABILITY June, 1991

```

- - - - -
|d|i|g|i|t|a|l|
|_|_|_|_|_|_|_|_|

```

FCO KA655-I001  
PAGE 2 OF 2

FIELD INSTALLATION:  
-----

1. Inspect the specified M7625-\*\* spares and order the appropriate EQ kits, (EQ-01614-01 rev "C1" or EQ-01614-02 rev "C1" as required, to ensure that all stock has been purged.
2. Place the new modules in the kit, and return old modules in the appropriate packing containers.

```

*****
*           NOTE           *
*
* The old M7625 modules are to be returned immediately to      *
* SR #126, via expedited transportation for upgrading.          *
*
*****

```

```

\\KA655
\^ KA655
\\FCO_DOCS
\\M7625
\\1991
\\JUN

```