

VT LAN40 Terminal

Regulatory Compliance Notices

FCC ID: A09-VTGYX

Note: The equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. Any changes or modifications made to this equipment may void the user's authority to operate this equipment.

This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment to an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Acoustic Noise Declaration

Preliminary declared values per ISO 9296 and ISO 7779 /DIN EN27779:

Product ^[1]	Sound Power Level		Sound Pressure Level ^[2]	
	L_{wAd} , B		L_{pAm} , dBA	
	Idle	Operate	Idle	Operate
VTLAN40	<3.3	<3.3	<21	<21

[1] Current values for specific configurations are available from service representatives. 1 B = 10 dBA.

[2] Operator position.

Schallemissionswerte

Vorläufige Werteangaben nach ISO 9296 und ISO 7779 /DIN EN27779:

Gerät ^[1]	Schalleistungspegel		Schalldruckpegel ^[2]	
	L_{wAd} , B		L_{pAm} , dBA	
	Leerlauf	Betrieb	Leerlauf	Betrieb
VTLAN40	<3,3	<3,3	<21	<21

[1] Aktuelle Werte für spezielle Ausrüstungsstufen sind über die Digital Equipment Vertretungen erhältlich. 1 B = 10 dBA.

[2] Bediener position.

